



Nr.	Part No	DESCRIPTION
1	PLBZ30.90	Compasso completo per torcia tipo - BINZEL® PSB 30 - Circle cutting attachment for BINZEL® PSB 30
	PLBZ30.90.1	Carrello per torcia tipo - BINZEL® PSB 30 - Cutting guide for BINZEL® PSB 30
2	PLBZ31.90	Compasso completo per torcia tipo - BINZEL® PSB 31/31KK - Circle cutting attachment for BINZEL® PSB 31/31KK
	PLBZ31.90.1	Carrello per torcia tipo - BINZEL® PSB 31/31KK - Cutting guide for BINZEL® PSB 31/31KK
3	PLBZ80.90	Compasso completo per torcia tipo - BINZEL® PSB 60/80/121 - Circle cutting attachment for BINZEL® PSB 60/80/121
	PLBZ80.90.1	Carrello per torcia tipo - BINZEL® PSB 60/80/121 - Cutting guide for BINZEL® PSB 60/80/121
4	PLCE50.90	Compasso completo per torcia tipo - CEBORA® 50/70 EWS-EX60 - Circle cutting attachment for CEBORA® 50/70 EWS-EX60
	PLCE50.90.1	Carrello per torcia tipo - CEBORA® 50/70 EWS-EX60 - Cutting guide for CEBORA® 50/70 EWS-EX60
5	PLCE90.90	Compasso completo per torcia tipo - CEBORA® 90 - Circle cutting attachment for CEBORA® 90
	PLCE90.90.1	Carrello per torcia tipo - CEBORA® 90 - Cutting guide for CEBORA® 90
6	PLCE150.90	Compasso completo per torcia tipo - CEBORA® 150 - EWS-EX100 - Circle cutting attachment for CEBORA® 150/EWS-EX100
	PLCE150.90.1	Carrello per torcia tipo - CEBORA® 150 - EWS-EX100 - Cutting guide for CEBORA® 150/EWS-EX100
7	PLHY40.90	Compasso completo per torcia tipo - HYPERTHERM® MAX 40/42 - Circle cutting attachment for HYPERTHERM® MAX 40/42
	PLHY40.90.1	Carrello per torcia tipo - HYPERTHERM® MAX 40/42 - Cutting guide for HYPERTHERM® MAX 40/42
8	PLHY100.90	Compasso completo per torcia tipo - HYPERTHERM® MAX 80/100 - Circle cutting attachment for HYPERTHERM® MAX 80/100
	PLHY100.90.1	Carrello per torcia tipo - HYPERTHERM® MAX 80/100 - Cutting guide for HYPERTHERM® MAX 80/100
9	PLSF24.90	Compasso completo per torcia tipo - SAF® CP 40 - CP 100 - Circle cutting attachment for SAF® CP 40 - CP 100
	PLSF24.90.1	Carrello per torcia tipo - SAF® CP 40 - CP 100 - Cutting guide for SAF® CP 40 - CP 100
10	PLTD51.90	Compasso completo per torcia tipo - THERMAL DYNAMICS® PCH/M 51 - Circle cutting attachment for THERMAL DYNAMICS® PCH/M 51
	PLTD51.90.1	Carrello per torcia tipo - THERMAL DYNAMICS® PCH/M 51 - Cutting guide for THERMAL DYNAMICS® PCH/M 51
11	PLTD52.90	Compasso completo per torcia tipo - THERMAL DYNAMICS® PCH/M 52 - Circle cutting attachment for THERMAL DYNAMICS® PCH/M 52
	PLTD52.90.1	Carrello per torcia tipo - THERMAL DYNAMICS® PCH/M 52 - Cutting guide for THERMAL DYNAMICS® PCH/M 52
12	PLTD100.90	Compasso completo per torcia tipo - THERMAL DYNAMICS® PCH/M 100 - Circle cutting attachment for THERMAL DYNAMICS® PCH/M 100
	PLTD100.90.1	Carrello per torcia tipo - THERMAL DYNAMICS® PCH/M 100 - Cutting guide for THERMAL DYNAMICS® PCH/M 100
13	PLTR30.90	Compasso completo per torcia tipo - TRAFIMET® S 30 - S 45 - Circle cutting attachment for TRAFIMET® S 30 - S 45
	PLTR30.90.1	Carrello per torcia tipo - TRAFIMET® S 30 - S 45 - Cutting guide for TRAFIMET® S 30 - S 45
14	PLTR81.90	Compasso completo per torcia tipo - TRAFIMET® A 81 - S 75 - Circle cutting attachment for TRAFIMET® A 81 - S 75
	PLTR81.90.1	Carrello per torcia tipo - TRAFIMET® A 81 - S 75 - Cutting guide for TRAFIMET® A 81 - S 75
15	PLTR914.90	Compasso completo per torcia tipo - TRAFIMET® A 90 - A 140 - Circle cutting attachment for TRAFIMET® A 90 - A 140
	PLTR914.90.1	Carrello per torcia tipo - TRAFIMET® A 90 - A 140 - Cutting guide for TRAFIMET® A 90 - A 140
16	PLTW90	Compasso completo per torcia tipo - TELWIN® PL 55/1 - 65/1 - 95/1 - Circle cutting attachment for TELWIN® PL 55/1 - 65/1 - 95/1
	PLTW90.1	Carrello per torcia tipo - TELWIN® PL 55/1 - 65/1 - 95/1 - Cutting guide for TELWIN® PL 55/1 - 65/1 - 95/1
	PL00.90.01	Rondella isolante per carrello - Insulating ring for cutting guide
	PL00.90.02	Kit COMPASSO senza carrello piccolo - Small box without cutting guide
	PL00.90.03	Kit COMPASSO senza carrello grande - Large box without cutting guide